



admin@mhcwd.org (530) 878-8096
16733 Placer Hills Road, PO Box 596, Meadow Vista, CA 95722

AGENDA

Special Board Meeting, April 24, 2026, at 2:00 P.M.

- ❖ The following agenda has been prepared and posted at least 24 hours prior to the special board meeting of the Midway Heights County Water District (MHCWD) Board of Directors in accordance with the Ralph M. Brown Act.
- ❖ The Board is prohibited by law from acting on any matter not appearing on the posted agenda, except in certain cases provided for in the Brown Act.
- ❖ In compliance with the Americans with Disabilities Act, if you are a disabled person and you need a disability-related modification or accommodation to participate in this meeting, please contact Teddi Deppner at (530) 878-8096 (phone) or board-secretary@mhcwd.org (email). Requests must be made as early as possible, and at least one full business day before the start of the meeting.
- ❖ In accordance with Government Code Sec. 54954.2(a), this notice and agenda were posted at the following locations: the MHCWD office, Meadow Vista Post Office, and Meadow Vista Village Center.

I. CALL TO ORDER

II. ROLL CALL OF DIRECTORS

Establish a quorum and identify for the minutes any other persons attending.

III. CLOSED SESSION - PUBLIC EMPLOYEE EMPLOYMENT - Govt. Code § 54957 Title: General Manager

IV. GENERAL BUSINESS

A. DISCUSSION & ACTION RE: IRRIGATION WATER PUMP REPLACEMENT

Discussion and possible approval of purchase of replacement irrigation water pump for Bridal Path pump station.

V. ANNOUNCEMENT OF NEXT REGULAR MEETING DATE & TIME

The next meeting, unless otherwise decided in session, will be held May 21, 2026, at 2:00 p.m. at the District Office.

VI. ADJOURNMENT

MEMORANDUM

TO: MHCWD BOARD OF DIRECTORS
FROM: Gerry LaBudde, Interim General Manager
RE: Irrigation Water Pump Replacement

RECOMMENDATION:

Immediate purchase of a replacement irrigation water pump for \$4,250 - \$4,750. Delivery lead time is 4-5 weeks, and District staff will install the new pump.

BACKGROUND:

There are two irrigation (raw) water pumps located in the pump station off of Bridal Path within the Coyote Hill area of the District. The pump station serves homes that are near the top of Coyote Hill which are above the District's raw water reservoir and treated water storage tanks.

The pump station conveys water up to the raw water storage tank that services approximately 10 customers and provides irrigation water and fire suppression for the area. The pump failed on February 8th, creating a large leak in the pump station.

The system is currently operating on the redundant raw water pump. If the second pump fails, there would be no means to pump the raw water to the tank. While steps may be available to use treated water to supply the raw water system, this would be much more costly and would require significant piping modifications at the tank site.

Goulds, the pump manufacturer, no longer manufactures replacement parts for this pump. Goulds does manufacture a similar pump with the same hydraulic output with nearly the same dimensions. Minimal changes to the piping system are anticipated. A local pump supplier provided a quote for \$9,676 for a replacement pump. The same pump model was found online for a cost of \$4,250 including shipping and taxes. Both quotes included a delivery lead time of 4-5 weeks, although that timing can change depending on the manufacturer's schedule and component availability.

District staff can install the new pump. The overall cost will be less than \$4,750 depending on whether any parts are needed to make modifications to the pump station piping to accommodate the new pump. Both quotes are attached.

MEMORANDUM

ATTACHMENT A – Flo-line Quote

ATTACHMENT B – Manufacturers Edge Quote



Flo-Line Technology, Inc.
 11822 Kemper Rd, Auburn, CA 95603
 Ph 530-887-2240, Fax 530-887-2243
www.flolinepumps.com

ATTENTION	GERRY LABUDDE
COMPANY	HYDROS ENGINEERING
EMAIL	GLABUDDE@HYDROS-ENGINEERING.COM
PHONE	530-906-5181
FAX	
CELL	530-906-5181
QUOTE NO	20260410
DATE	03-10-2026

PREPARED BY	AKELA TAYLOR	LEAD TIME	4-6 WEEKS
CELL	530-887-2240	FREIGHT	PP&ADD
E-MAIL	AKELA@FLOLINEPUMPS.COM	SHIP VIA	BEST WAY
SUBJECT	GOULDS 3SVBK4 PUMP E&R	TERMS	NET 30 O.A.C.
REFERENCE	SN: C0019034	VALIDITY	30 DAYS

Qty	Part No	Description	Unit Price	Ext'd
		GOULDS 3SVBK4 PUMP, SN C0019034 E&R		
1	10SV5FG4C50	GOULDS PUMP 10SV5FG4C50 - 5HP, 3600RPM, 60Hz, 3 PHASE, DPPE 360, 5 STG	\$9,676.00	\$9,676.00
	LEAD TIME	4-6 WEEKS		
		AS STATED IN THE REPORT, PUMP AND REPLACEMENT PARTS ARE OBSOLETE		
		FREIGHT AND TAXES NOT INCLUDED.		
		ALL SALES ARE FINAL!		

<i>THANK YOU VERY MUCH FOR THE OPPORTUNITY TO QUOTE THE ABOVE PRODUCTS</i>			Total	\$9,676.00
--	--	--	-------	------------



Flo-Line Technology, Inc.
 11822 Kemper Rd, Auburn, CA 95603
 Ph-530-887-2240, Fax 530-887-2240
sales@flolinepumps.com

Quote #	20260410	Job #	260221
---------	----------	-------	--------

PUMP EVALUATION REPORT

Customer		Date	3/5/2026
----------	--	------	----------

Name	HYDROS ENGINEERING	Contact	GERRY LaBUDE	Phone	530-906-5181
------	--------------------	---------	--------------	-------	--------------

Pump Eq't

Make	GOULDS	Model	3SVBK4	Serial#	C0019034
------	--------	-------	--------	---------	----------

Motor

Notes	N/A	HP	N/A	RPM	N/A	Phase	N/A	Volts	N/A
-------	-----	----	-----	-----	-----	-------	-----	-------	-----

Problem-detailed and specific:
 CUSTOMER BROUGHT PUMP TO FLO-LINE TO REPLACE MECHANICAL SEAL AS THEY DID NOT WANT TO DAMAGE THE PUMP. CUSTOMER HAS MECHANICAL SEAL.

Inspection Report Summary:
 UPON INSPECTION, TECHNICIAN REMOVED THE TOP HOUSING AND THE COUPLING GUARD AND NOTICED THE INSIDE OF THE PUMP IS COATED IN RUST AND DEBRIS. ONCE THE SHAFT WAS EXPOSED TECHNICIAN INSPECTED THE MECHANICAL SEAL AND FOUND IT TO BE TORN AND WARPED. TECHNICIAN REMOVED MECHANICAL SEAL AND ALL 3 STAGES OF IMPELLERS AND DIFFUSER PLATES. THE SLEEVES ON THE SHAFT IN BETWEEN IMPELLERS WERE ALL WARPED. TECHNICIAN THEN REMOVED THE SHAFT AND NOTICED THE TUNGSTEN CARBIDE SLEEVE WAS BROKEN INTO PIECES. THE CERAMIC BUSHING IT RIDES ON IS ALSO DAMAGED FROM THE SLEEVE FAILING. THE SHAFT HAS SCORING FROM FAILING PARTS CONTACTING IT DURING OPERATION.

PARTS NEEDED FOR REPAIR:
 THE PUMP AND THE PARTS NEEDED FOR REPAIR ARE OBSOLETE.

Estimated Repair Cost

Mat'l		Labor hrs	2	labor cost		Freight		Total	
-------	--	-----------	---	------------	--	---------	--	-------	--

Warranty determination:
 Yes No Partial

Repair/Replacement covered by %
 customer 100% principal Flo-line

Prepared By	CODY WILLIS	Date	3/5/2026	CW
-------------	-------------	------	----------	----



REMIT TO: Manufacturers Edge
 5044 Industrial Rd.
 Suite C
 Farmingdale NJ 07727
 United States

Quote	
Quote #:	Q-00280940
Date Quote:	3/30/2026
Expiry Date:	6/28/2026
Sales Rep:	Ponicsan Matthew Email: matt@pumpcatalog.com Phone: +17323720678
Prepared For:	Gerry LaBudde Email: glabudde@hydros-engineering.com Phone: +15306374441

Bill To: Hydros Engineering
 P.O. Box 598
 Weimar CA 95736
 United States

Credit Terms: CREDIT CARD

Customer Notes: PER YOUR REQUEST
 10SV5FG4C50

Ship To: Midway Heights County Water District
 20677 Nature's Way
 Colfax CA 95713
 United States

Shipping In: in 4-5 weeks

Shipping Method: BEST WAY

Quantity	Product Code	Line Item Description	Unit Price	Total Price
1	10SV5FG4C50	10SV5FG4C50 Goulds Pump e-SV Stainless Steel Vertical Multi-Stage, 5 HP, 2 Pole / 60 Hz / 3 PH, DPPE - Open Drop Proof Motor (Premium Efficient), 360 PSIG, 5 Stage	3,608.05	3,608.05

Subtotal	3,608.05
Shipping	355.90
Sales Tax	261.58
Total	4,225.53

NOTE: These items are Non-Refundable

Thank you for the opportunity to provide you with the following quotation.

For your reference, please visit <https://www.pumpcatalog.com/pages/terms-conditions/> for Terms & Conditions

Please Note: Pricing is subject to change without notice.

Availability is based on an inventory snapshot and is subject to prior sales.